

HABS
KY
106-SHELBY,
3-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

Thomas Threlkeld House
Benson Pike
Shelbyville vicinity
Shelby County
Kentucky

HABS No. KY-204

Nathan Pritchard, photographer Summer 1981

- KY-204-1 SOUTH FRONT OF ORIGINAL SECTION (ca. 1815). NOTE THE FOLLOWING:
1) TRACES OF OLD PORCH AROUND DOOR 2) TWO KINDS OF CORNICES
3) BASEMENT VENTS 4) HORIZONTAL BEADED WEATHERBOARDS (see
also KY-204-2 and KY-204-3) 5) STONE CHIMNEY ON EAST SIDE
6) WEST STONE WING AT LEFT.
- KY-204-2 SOUTH FRONT DOOR OF ORIGINAL SECTION. Probably original.
- KY-204-3 DETAIL OF WEST WINDOW OF SOUTH FRONT OF ORIGINAL SECTION. NOTE
FRAME AND SHUTTER HARDWARE. Original sash probably double-hung.
- KY-204-4 DETAIL OF SPLAYED WINDOW OF SOUTH FRONT OF WEST STONE WING.
(see also KY-204-7 for interior view).
- KY-204-5 DETAIL OF MUD INFILL (MIXED WITH STRAW), LATHS AND STRUCTURAL
COMPONENTS (CORNER POST, SILL AND STUD), SOUTHEAST CORNER
OF EAST SIDE OF ORIGINAL SECTION.
- KY-204-6 CA. 1815-16 FEDERAL WOOD MANTLE, WEST WALL OF WEST STONE WING.
- KY-204-7 INTERIOR SIDE OF SPLAYED WINDOW OF SOUTH FRONT OF WEST STONE
WING. NOTE paneled JAMBS AND HEAD. (see also KY-204-4 for
exterior view).
- KY-204-8 EAST GARRET WALL (EAST GABLE END) OF ORIGINAL SECTION, WITH
HORIZONTAL BEADED SIDING AND CASEMENT SASH.
- KY-204-9 DETAIL OF ORIGINAL CASEMENT SASH, NORTHEAST PART OF EAST GARRET
WALL (EAST GABLE END).